


MODEL : 50CR2. 4S

BORE	OUT PUT		POLES	RPM	PHASE	VOLTAGE	HZ	RATED AMPERAGE	STARTING AMPS	STARTING METHOD	INS. CLASS	SOLIDS DIA.
	HP	KW										
2" (50mm)	1/2	0.4	2	3453	1	115	60	5.5	29.90	Capacitor Run	E	1 1/4" (35mm)

MODEL : 50CR2. 4T

BORE	OUT PUT		POLES	RPM	PHASE	VOLTAGE	HZ	RATED AMPERAGE	STARTING AMPS	STARTING METHOD	INS. CLASS	SOLIDS DIA.
	HP	KW										
2" (50mm)	1/2	0.4	2	3440	3	230	60	2.0	12.73	DIRECT	E	1 1/4" (35mm)



DWG.	M. Tsurui	· ·	TITLE PERFORMANCE CURVE	DWG No. Y31943
JUDG.		· ·		
APPD.		· ·		