
Watts Half Turn Mount Potential "Gurgle" Issues



If the diffuser is not properly installed, the air disperser will allow a loud "gurgle" noise to be created when the RO is making water. Customer needs to check and verify white diffuser is present and is installed correctly.